

PRODUCT MODIFICATION

New fins for anti-rotation of cable gland

As of May 8th 2017

Date of communication: May 8, 2017

Series affected by the change: TH391, TH387, TH392

Part numbers affected:

THx.391.xxx / THx.391.xxx.R / THx.391.xxx.L / THx.391.xxx.L.R
THx.392.xxx / THx.392.xxx.R / THx.392.xxx.L / THx.392.xxx.L.R
THx.387.xxx / THx.387.xxx.R / THx.387.xxx.L / THx.387.xxx.L.R
THx.387.xxx.XD / THx.387.xxx.LXD

Description of the modification:

The design of the product has been modified with the addition of plastic protrusions (fins) at each conductor connection hole in each polarity. The fins have been added to all products in the TH391, TH392 and TH387 series articles (see example for TH391 in the figure below).

The new design of the product guarantees the anti-rotation functionality of the cable gland which is available only for TH391, TH392 and TH387 connectors with part number containing the letter "L" (cable gland for cables of diameter from 7.0 mm to 13.5 mm).

Changes do not compromise other product features and assembly phases.

It is also guaranteed the total compatibility between products with the new design and products with the previous design and any accessories for the products subject to the above changes.

Date of availability of the new version: immediate. (Note: products of previous version are running out of stock).

Technical drawings:

Download the following technical drawings showing the changes made.

For more information, please contact our Customer Service at customerservice@techno.it or phone us at +39 031 976445 (ext. 224).

https://www.techno.it/gallery/1800/Techno_TH391_Newdesign.PDF

https://www.techno.it/gallery/1800/Techno_TH392_Newdesign.PDF

https://www.techno.it/gallery/1800/Techno_TH387_Newdesign.PDF

